

INTERIM STATEMENT

AIRBUS A330-300, REGISTRATION 9V-SSE ENGINE FAILURE DURING CRUISE 7 FEBRUARY 2018

The information provided herein is of an interim nature. Readers are advised that new information may become available that may alter this interim statement prior to the publication of the Final Report.

On 7 February 2018, at about 1630hrs Singapore time, an Airbus A330-300 aircraft flying from Dhaka, Bangladesh, to Singapore experienced the left hand engine failure while climbing through 30,000 feet. The aircraft diverted to Mandalay International Airport in Myanmar without further incident. There was no injury to any person.

After landing, the fan blades and fan case of the left hand engine were found to have been damaged.

The occurrence was classified as an incident.

The investigation team is drafting the investigation report.

21 February 2019